


SCHEMATIC DIAGRAM



THE SYMBOL MARK OF THIS SCHEMATIC DIAGRAM INCORPORATES SPECIAL FEATURES IMPORTANT FOR PROTECTION FROM X-RADIATION FILTRATION AND ELECTRICAL SHOCK HAZARDS. WHEN SERVICING IF IS ESSENTIAL THAT ONLY MANUFACTURER SPECIFIED PARTS BE USED FOR THE CRITICAL COMPONENTS IN THE SYMBOL MARK OF THE SCHEMATIC.

COMPANY	CONFIDENTIAL DO NOT COPY!
DATE	2002-08-26
REV	01
MODEL	CB7771-1, 1inchong
Sheet	1
Page	1